

MODEL NO. : LM-1050HD 10.4" Waterproof Monitor


□ SPECIFICATION □

◆ DISPLAY SCREEN	SIZE	10.4 INCH
	Active Area	211.2(W) x 158.4 mm(H)
	ELEMENT	COLOR TFT LCD
	RESOLUTION	800 x 600
	DOT PITCH	0.264 (W) x 0.264 (H)mm
◆ POWER SOURCE	DC 12V	
◆ POWER CONSUMPTION	10W Typ.	
◆ OPERATING TEMPERATURE	0°C ~ 50°C	
◆ STORAGE TEMPERATURE	-20°C ~ 60°C	
◆ BRIGHTNESS	230 cd/m ²	
◆ CONTRAST	500 : 1	
◆ OPTICAL RISE TIME/FALL TIME	10/25 Typ.	
◆ VIEWING ANGLE	Vertical +35° /-65° , Horizontal : ± 60°	
◆ PC INPUT	RGB Analogue Input 15Pin D-sub x 1	
◆ VIDEO INPUT	1Vpp 75Ω, RCA x 1, HDMI x 1.	
◆ PLUG & PLAY	VESA DDC2B	
◆ GREEN FUNCTION	VESA DPMS	
◆ OSD CONTROL FUNCTION	Brightness, Contrast, Color, Volume, Mute	
◆ LCD SCREEN	305.0 x 256.0 x 44 (mm)	
◆ WEIGHT	3Kg	

□ FEATURE □

- ◆ Waterproof
- ◆ 10.4" Industrial LCD Screens
- ◆ 1 x Video RCA Inputs
- ◆ 1x HDMI Input
- ◆ Low Power Consumption
- ◆ 5 Wire Resistive Touch Screen (Optional)
- ◆ High Brightness 1000 Nit or 1500 Nit (Optional)
- ◆ Single Key Brightness Control
- ◆ Hot Key for Input Source Select

▢ ON SCREEN DISPLAY SETTINGS (OSD) ▢



- ◆ To turn on the OSD menu: Press power button.
Press Menu button.
- ◆ When OSD menu is on
 - Select option within icon menu: Use up or down buttons.
Then press Menu to make select.
 - Increase/decrease setting : Use up or down buttons.
- ◆ To load the presetting (default setup) :
Use menu button and power button. (menu +power button)

MECHANICAL DRAWING

◆ Monitor Dimension

